Appendix C. Setup Photographs

<Radiated Emission>

Z Plane for Part22H/27L

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : C1 of C2
Report Issued Date : Sep. 30, 2017
Report Version : Rev. 01

Report Template No.: BU5-FG22/24/27 Version 1.2


Report No.: FG790406A

Y Plane for Part24E

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLULIFEONEX3 Page Number : C2 of C2
Report Issued Date : Sep. 30, 2017
Report Version : Rev. 01

Report No.: FG790406A

Report Template No.: BU5-FG22/24/27 Version 1.2