

Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E1 of E3
Report Issued Date : Jun. 26, 2018
Report Version : Rev. 01

Report No.: FR853112C

Report Template No.: BU5-FR15CWL AC MA Version 2.0



Report No.: FR853112C

For adapter


<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E2 of E3
Report Issued Date : Jun. 26, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL AC MA Version 2.0



FCC RF Test Report

For wireless charging

X Plane

ΗF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E3 of E3
Report Issued Date : Jun. 26, 2018
Report Version : Rev. 01

Report No.: FR853112C

Report Template No.: BU5-FR15CWL AC MA Version 2.0