
Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : A1 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC621907

<Radiated Emission>

Mode 3

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : A2 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3


Report No.: FC621907

C Test Report No. : FC621907


Mode 4

X Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUNEOEMINI Page Number : A3 of A3
Report Issued Date : Apr. 14, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3