

Appendix B. Setup Photographs


<Radiated Emission>

H Plane

Low Frequency



High Frequency



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTANK Page Number : B1 of B2
Report Issued Date : Jul. 02, 2012
Report Version : Rev. 01


Report No.: FG252806




Report No.: FG252806

<Radiated Emission> E2 Plane

Low Frequency



High Frequency



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUTANK

Page Number : B2 of B2 Report Issued Date: Jul. 02, 2012 Report Version : Rev. 01