

Report No.: FA3N1202

## Appendix D. SAR Test Setup Photos






**Right Cheek** 









Left Cheek

**Left Tilted** 







Back, Test Separation 1 cm

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUSTUDIO5II Page Number : D1 of D2 Report Issued Date: Dec. 13, 2013

Report Version : Rev. 01






Left Side, Test Separation 1 cm



Report No.: FA3N1202


Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm



Back, Test Separation 1 cm (with / Headset)

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FAX: +86-029-8860-8791 FCC ID: YHLBLUSTUDIO5II Page Number : D2 of D2 Report Issued Date: Dec. 13, 2013 Report Version : Rev. 01