
# Appendix A. Setup Photographs

## <Conducted Emission>

#### Mode 1





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8 Page Number : A1 of A3
Report Issued Date : Jun. 15, 2017
Report Version : Rev. 01


Report No.: FC750505

Report Template No.: BU5-FC15B Version 1.3



Mode 5





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8 Page Number : A2 of A3
Report Issued Date : Jun. 23, 2017
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC750505


# <Radiated Emission>

## Mode 5

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVO8 Page Number : A3 of A3
Report Issued Date : Jun. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No.: FC750505