
Appendix A. Setup Photographs


<Radiated Emission>

Y Plane for 22H

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55 Page Number : A1 of A3
Report Issued Date : Jun. 12, 2015
Report Version : Rev. 01

Report No.: FG551303


Report No. : FG551303

Z Plane for 24E

LF




HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55 Page Number : A2 of A3
Report Issued Date : Jun. 12, 2015
Report Version : Rev. 01

X Plane for 27L

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTC55 Page Number : A3 of A3
Report Issued Date : Jun. 12, 2015
Report Version : Rev. 01

Report No.: FG551303