


## Appendix B. Setup Photographs

## <Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number : B1 of B2
Report Issued Date Jan. 23, 2018
Report Version : Rev. 01

Report No.: FR7D2005A

Report Template No.: BU5-FR15CBT Version 2.0




## <Radiated Emission>

X Plane LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number : B2 of B2
Report Issued Date Jan. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR7D2005A