

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : B1 of B2 Report Issued Date : Jan. 05, 2015

Report No.: FR4N1408C

Report Version : Rev. 01




## Report No.: FR4N1408C

## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : B2 of B2
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01