
## Appendix A. Setup Photographs


## <Radiated Emission>

Y Plane For 22H

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE54 Page Number : A1 of A3
Report Issued Date : Nov. 27, 2015
Report Version : Rev. 01


Report No.: FG5O0914A

## **Z Plane For 24E**

LF



HF




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE54 Page Number : A2 of A3
Report Issued Date : Nov. 27, 2015
Report Version : Rev. 01


Report No.: FG500914A

## Z Plane For 27L

LF



HF



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEONE54 Page Number : A3 of A3
Report Issued Date : Nov. 27, 2015
Report Version : Rev. 01

Report No.: FG500914A