
Appendix C. Setup Photographs


<Radiated Emission>

Z Plane for 22H

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTONEPLUS Page Number : C1 of C3
Report Issued Date : Nov. 30, 2015
Report Version : Rev. 01


Report No. : FG5O1206A

Y Plane for 24E

LF



HF




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTONEPLUS Page Number : C2 of C3
Report Issued Date : Nov. 30, 2015
Report Version : Rev. 01


Report No.: FG5O1206A

X Plane for 27L

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTONEPLUS Page Number : C3 of C3
Report Issued Date : Nov. 30, 2015
Report Version : Rev. 01

Report No.: FG5O1206A