Appendix A. Setup Photographs

<Conducted Emission>

Mode 1



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMINILTE Page Number : A1 of A3
Report Issued Date : Nov. 25, 2014


Report No.: FR482608C

Report Version : Rev. 01


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMINILTE Page Number : A2 of A3
Report Issued Date : Nov. 25, 2014
Report Version : Rev. 01

Report No. : FR482608C


Report No. : FR482608C

Z Plane

LF







SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMINILTE Page Number : A3 of A3
Report Issued Date : Nov. 25, 2014
Report Version : Rev. 01