3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.0 S; Marketing Name: Studio 5.0 S

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 11 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 12 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 13 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 14 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 15 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 16 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 17 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01


Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 18 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Describing Bill Madel News Of the FO.O. Madel (from News Of the FO.)

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 19 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 20 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 21 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 22 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 23 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 24 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: EP332505



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO50S Page Number : 25 of 25
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01