


Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : B1 of B2
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report No.: FR632501A

Report Template No.: BU5-FR15CBT Version 1.1




Report No.: FR632501A


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHL2 Page Number : B2 of B2
Report Issued Date : May 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1