


Report No.: FR7D2005C

Appendix D. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number D1 of D2 Report Issued Date : Jan. 23, 2018 Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 2.0



Report No.: FR7D2005C


<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXLIII Page Number D2 of D2
Report Issued Date : Jan. 23, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0