

Report No. : FA361702

Appendix D. Test Setup Photos





Right Cheek

Right Tilted





Left Cheek

Left Tilted

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZOEY Page Number : D1 of D2
Report Issued Date : Jul. 18, 2013
Report Version : Rev. 01



FCC SAR Test Report



Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

Report No. : FA361702

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUZOEY Page Number : D2 of D2
Report Issued Date : Jul. 18, 2013
Report Version : Rev. 01