
3. Internal Photograph of EUT

Brand Name: BLU / Model Name: VIVO AIR


Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 12 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01



Report No.: EP4N1408




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR

: 13 of 28 Page Number Report Issued Date : Jan. 05, 2015 : Rev. 01 Report Version


Report No.: EP4N1408

Brand Name: BLU / Model Name: VIVO AIR



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 14 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01


Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 15 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01




Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 16 of 28 Report Issued Date : Jan. 05, 2015 Report Version : Rev. 01




Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 17 of 28 Report Issued Date : Jan. 05, 2015 Report Version : Rev. 01



Report No.: EP4N1408




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR

: 18 of 28 Page Number Report Issued Date : Jan. 05, 2015 Report Version : Rev. 01



Report No.: EP4N1408




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR

: 19 of 28 Page Number Report Issued Date : Jan. 05, 2015 : Rev. 01 Report Version




Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR

: 20 of 28 Page Number Report Issued Date : Jan. 05, 2015 : Rev. 01 Report Version


Report No.: EP4N1408



SPORTON INTERNATIONAL (SHENZHEN) INC.


TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 21 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01

Report No.: EP4N1408




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 22 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01

Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 23 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01


Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 24 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01




Report No.: EP4N1408




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 25 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01

Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 26 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01

Report No.: EP4N1408




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR Page Number : 27 of 28
Report Issued Date : Jan. 05, 2015
Report Version : Rev. 01



Report No.: EP4N1408



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUVIVOAIR

: 28 of 28 Page Number Report Issued Date : Jan. 05, 2015 : Rev. 01 Report Version