
# Appendix A. Setup Photographs

# <Conducted Emission>

#### Mode 3



Mode 4



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGRAND55HD Page Number : A1 of A3
Report Issued Date : May 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3

Report No. : FC640702

# <Radiated Emission>

## Mode 1

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGRAND55HD Page Number : A2 of A3
Report Issued Date : May 20, 2016
Report Version : Rev. 01


Report Template No.: BU5-FC15B Version 1.3

Report No.: FC640702


Report No. : FC640702

## Mode 4

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGRAND55HD Page Number : A3 of A3
Report Issued Date : May 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FC15B Version 1.3