


Appendix E. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E1 of E3
Report Issued Date Jun. 26, 2018
Report Version : Rev. 01

Report No.: FR853112B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 2.0




<Radiated Emission>

X Plane for adapter mode

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E2 of E3
Report Issued Date Jun. 26, 2018
Report Version : Rev. 01

Report No.: FR853112B

Report Template No.: BU5-FR15CBT4.0/4.2 Version 2.0



Report No. : FR853112B

X Plane for wireless charging mode



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXIP Page Number : E3 of E3
Report Issued Date Jun. 26, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0/4.2 Version 2.0