


Report No. : FA411005

Appendix D. Test Setup Photos



Right Cheek



Right Tilted

Left Cheek Left Tilted

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUHEROJR Page Number : D1 of D2
Report Issued Date : Feb. 21, 2014

Report Version : Rev. 01







Report No. : FA411005

Front of the DUT with Phantom 1.5 cm Gap

Back of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUHEROJR Page Number : D2 of D2
Report Issued Date : Feb. 21, 2014
Report Version : Rev. 01