

Report No.: FR870301A

Appendix E. Setup Photographs

<Conducted Emission>





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXI

Page Number : E1 of E2 Report Issued Date Jul. 23, 2018 Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0




<Radiated Emission>

Z Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: YHLBLUVIVOXI Page Number : E2 of E2
Report Issued Date Jul. 23, 2018
Report Version : Rev. 01

Report No.: FR870301A

Report Template No.: BU5-FR15CBT Version 2.0