

# Appendix B. Setup Photographs

## <Conducted Emission>

#### Mode 1



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHX2 Page Number : B1 of B2
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 1.1


Report No.: FR612803A




### <Radiated Emission>

#### **Z** Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUDASHX2 Page Number : B2 of B2
Report Issued Date : Mar. 16, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1

Report No.: FR612803A