1. External Photograph of EUT

Brand Name: BLU / Model Name: Deejay

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 1 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Durand Names Dill / Madal Names Desires

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 2 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ

Page Number : 3 of 33 Report Issued Date : Sep. 27, 2010 Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 4 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 5 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 6 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

2. Photograph of Accessory

Brand Name: BLU / Model Name: Deejay

Report No.: EP090824

List of Accessory:

Specification of Accessory		
IAC Adapter	Brand Name	BLU
	Model Name	Deejay
IBattery	Brand Name	BLU
	Model Name	Deejay
Earphone	Signal Line Type	1.3 meter non-shielded cable without ferrite core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 7 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 8 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 9 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 10 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 11 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 12 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01


Report No.: EP090824



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 13 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 14 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01

Report No.: EP090824



TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLBLUDJ Page Number : 15 of 33
Report Issued Date : Sep. 27, 2010
Report Version : Rev. 01