Appendix D. SAR Test Setup Photos






Report No. : FA7D2005

Right Cheek

Right Tilted





Left Cheek **Left Tilted**

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595


: Jan. 23, 2018 : 170509 FCC ID: YHLBLUVIVOXLIII Page D1 of D2 Form version.

Issued Date


Report No.: FA7D2005

Front, Test Separation 10 mm


Back, Test Separation 10 mm




Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595

FCC ID: YHLBLUVIVOXLIII

Issued Date Form version. : Jan. 23, 2018

Page D2 of D2

: 170509