1. External Photograph of EUT

Brand Name: BLU / Model Name: Lindy B

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 1 of 32 Report Issued Date : Mar. 05, 2012

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 2 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB

: 3 of 32 Page Number Report Issued Date : Mar. 05, 2012

: Rev. 01 Report Version

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 4 of 32 Report Issued Date : Mar. 05, 2012

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB

: 5 of 32 Page Number Report Issued Date : Mar. 05, 2012 : Rev. 01

Report Version

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 6 of 32 Report Issued Date : Mar. 05, 2012

2. Photograph of Accessory

Brand Name: BLU / Model Name: Lindy B

Report No.: EP221003

List of Accessory:

Specification of Accessory		
IAC Adapter	Brand Name	BLU
	Model Name	US200507
IBattery	Brand Name	BLU
	Model Name	N5B50T
Earphone	Туре	1.30 m non-shielded without core

Remark: For accessories equipped with this EUT, please refer to the following photos.

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 7 of 32
Report Issued Date : Mar. 05, 2012

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 8 of 32 Report Issued Date : Mar. 05, 2012

Report No.: EP221003

Brand Name: BLU / Model Name: Lindy B



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 9 of 32 Report Issued Date : Mar. 05, 2012 Report Version : Rev. 01

Report No.: EP221003

Brand Name: BLU / Model Name: Lindy B



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 10 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01


Report No.: EP221003



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 11 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 12 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01


Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 13 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01




Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 14 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 15 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01

Report No.: EP221003



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : 16 of 32
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01