

Appendix B. Setup Photographs

<Conducted Emission> Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : B1 of B2
Report Issued Date : Jul. 01,2013
Report Version : Rev. 01


Report No.: FR342511C





<Radiated Emission>

LF





HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASH45 Page Number : B2 of B2 Report Issued Date: Jul. 01,2013 Report Version : Rev. 01

Report No.: FR342511C