


Report No. : FG052523


Appendix B. Setup Photographs

<Radiated Emission>

E1 Plane



Front View




Rear View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B1 of B3
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01




Report No.: FG052523



Remote View

E2 Plane



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B2 of B3
Report Issued Date : Jun. 25, 2010
Report Version : Rev. 01






Report No.: FG052523

Rear View





Remote View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: +86-0512-5790-0158 FAX: +86-0512-5790-0958 FCC ID: YHLCTBLUTATTOO Page Number : B3 of B3 Report Issued Date : Jun. 25, 2010 Report Version : Rev. 01