

Report No. : FA210505

Appendix D. Product Photos





TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCHARLES Page Number : D1 of D1
Report Issued Date : Feb. 07, 2012
Report Version : Rev. 01



Report No.: FA210505

Appendix E. **Test Setup Photos**





Right Cheek









Left Cheek

Left Tilted





Face of the DUT with Phantom 1.5 cm Gap

Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUCHARLES Page Number : E1 of E1 Report Issued Date: Feb. 07, 2012 Report Version : Rev. 01