


Report No.: FA221003

Appendix D. Product Photos









TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : D1 of D1
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01



Report No.: FA221003


Appendix E. Test Setup Photos





Right Cheek










Left Tilted



Face of the DUT with Phantom 1.5 cm Gap



Bottom of the DUT with Phantom 1.5 cm Gap

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLULINDYB Page Number : E1 of E1
Report Issued Date : Mar. 05, 2012
Report Version : Rev. 01