

## Report No. : FR1N1201B

# Appendix B. Setup Photographs

# <Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158

FAX: 86-0512-5790-0958

FCC ID: YHLBLUTOUCHBOOK


Page Number : B1 of B2
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01






Report No. : FR1N1201B

#### <Radiated Emission>



LH

HF



### SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUTOUCHBOOK Page Number : B2 of B2
Report Issued Date : Dec. 06, 2011
Report Version : Rev. 01