

Report No.: FA090827

Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : D1 of D1
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01



Report No.: FA090827

Appendix E. Test Setup Photos



Right Cheek







Left Cheek Left Tilted







Bottom of the DUT with Phantom 1.5 cm Gap

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSAMBMN Page Number : E1 of E1
Report Issued Date : Sep. 28, 2010
Report Version : Rev. 01