

Appendix B. Setup Photographs

<Conducted Emission>

Mode 2



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : B1 of B3
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01

Report No. : FC311501



Report No. : FC311501


<Radiated Emission>

Mode 1

LF



HF




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : B2 of B3
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01






Mode 4

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSPARKTV Page Number : B3 of B3
Report Issued Date : Mar. 05, 2013
Report Version : Rev. 01

Report No. : FC311501