

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : B1 of B2 Report Issued Date : May 26, 2015


Report No.: FR531002B

Report Version : Rev. 01




<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTMNLTE2 Page Number : B2 of B2
Report Issued Date : May 26, 2015
Report Version : Rev. 01

Report No.: FR531002B