



Report No. : FA390601

Appendix D. SAR Test Setup Photos





Right Cheek








Left Cheek

Left Tilted





Front, Test Separation 1 cm

Back, Test Separation 1 cm

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FCC ID: YHLBLUSTUDIO55 Page Number : D1 of D2
Report Issued Date : Oct. 11, 2013
Report Version : Rev. 01










Report No. : FA390601

Bottom Side, Test Separation 1 cm



Top Side, Test Separation 1 cm



Right Side, Test Separation 1 cm

TEL: +86-029-8860-8767 FCC ID: YHLBLUSTUDIO55 Page Number : D2 of D2
Report Issued Date : Oct. 09, 2013
Report Version : Rev. 01