

<Conducted Emission>

Appendix B. Setup Photographs

Mode 3



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B1 of B3
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: FD332505



Mode 4




TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B2 of B3
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01


Report No.: FD332505



<Radiated Emission> Low Frequency



High Frequency



TEL: +86-755- 3320-2398 FCC ID: YHLBLUSTUDIO50S Page Number : B3 of B3
Report Issued Date : Apr. 19, 2013
Report Version : Rev. 01

Report No.: FD332505