

## Appendix B. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : B1 of B2
Report Issued Date : Mar. 29, 2013
Report Version : Rev. 01

Report No.: FR330701A







<Radiated Emission>

<Radiated Emission>

LF





HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO53S Page Number : B2 of B2 Report Issued Date : Mar. 29, 2013

Report No.: FR330701A

Report Version : Rev. 01