

Report No.: FA383001


## Appendix D. SAR Test Setup Photos





**Right Cheek** 

**Right Tilted** 





Left Cheek

Left Tilted






Front, Test Separation 1 cm

Back, Test Separation 1 cm

SPORTON INTERNATIONAL (XI'AN) INC.

TEL: +86-029-8860-8767 FCC ID: YHLBLULIFEPRO Page Number : D1 of D2
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01





Left Side, Test Separation 1 cm

**Bottom Side, Test Separation 1 cm** 

**Report No. : FA383001** 



Top Side, Test Separation 1 cm

TEL: +86-029-8860-8767 FCC ID: YHLBLULIFEPRO Page Number : D2 of D2
Report Issued Date : Sep. 24, 2013
Report Version : Rev. 01