

Report No. : FD1D0107

Appendix B. Setup Photographs

<Conducted Emission>



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITE Page Number : B1 of B2
Report Issued Date : Dec. 09, 2011
Report Version : Rev. 01






Report No.: FD1D0107

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDJLITE Page Number : B2 of B2
Report Issued Date : Dec. 09, 2011
Report Version : Rev. 01