

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Front View

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B1 of B2 Report Issued Date: Jan. 06, 2012

Report No.: FR1D0806B

Report Version : Rev. 01




Report No. : FR1D0806B

<Radiated Emission>



LF



HF

SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO Page Number : B2 of B2
Report Issued Date : Jan. 06, 2012
Report Version : Rev. 01