
3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Dash 5.5

Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 11 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 12 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01




Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 13 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01



Report No.: EP460302




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 14 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01



Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 15 of 31 Report Issued Date : Jul. 17, 2014 : Rev. 01 Report Version







TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 16 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01



Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 17 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01






SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 18 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01


Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 19 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01




Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 20 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01

Report No.: EP460302




SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 21 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01




Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 22 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01




Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 23 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01




Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 24 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01




Report No.: EP460302




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 25 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01

Report No.: EP460302




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 26 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01

Report No.: EP460302




TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 27 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01

Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 28 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01

Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 29 of 31
Report Issued Date : Jul. 17, 2014
Report Version : Rev. 01







TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 30 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01



Report No.: EP460302



TEL: 86-755-3320-2398 FCC ID: YHLBLUDASH55 Page Number : 31 of 31 Report Issued Date : Jul. 17, 2014 Report Version : Rev. 01