

Report No. : FA281501

Appendix D. Product Photos




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO43 Page Number : D1 of D2
Report Issued Date : Aug. 29, 2012
Report Version : Rev. 01



Report No. : FA281501

Antenna Location:



Antenna	Length	Width
WWAN Antenna (Tx / Rx)	4.5 cm	1.4 cm
BT&WLAN Antenna (Tx / Rx) & GPS Antenna (Rx)	2.1 cm	2.1 cm
EUT	12.7 cm	6.7 cm

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO43 Page Number : D2 of D2
Report Issued Date : Aug. 29, 2012
Report Version : Rev. 01



Report No. : FA281501

Appendix E. **Test Setup Photos**





Right Cheek


Right Tilted



Left Cheek



Left Tilted



Front of the DUT with Phantom 1.5 cm (with Headset)



Back of the DUT with Phantom 1.5 cm Gap (with Headset)

SPORTON INTERNATIONAL (KUNSHAN) INC

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUVIVO43 Page Number : E1 of E1 Report Issued Date: Aug. 29, 2012 Report Version : Rev. 01