Appendix D. SAR Test Setup Photos






Report No.: FA883001

Right Cheek

Right Tilted





Left Cheek Left Tilted

Sporton International (Shenzhen) Inc.




Front, Test Separation 10 mm




Report No. : FA883001


Back, Test Separation 10 mm



Left Side, Test Separation 10 mm



Right Side, Test Separation 10 mm



Top Side, Test Separation 10 mm



Bottom Side, Test Separation 10 mm

Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 / FAX: +86-755-8637-9595

FCC ID: YHLBLUVIVOXL4

Issued Date

Page D2 of D2

: Sep. 28, 2018 : 170509

Form version.