

Appendix D. Setup Photographs

<Conducted Emission>



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : D1 of D2
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report No.: FR651207C


Report Template No.: BU5-FR15CWL Version 1.3



<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUSTDC88LTE Page Number : D2 of D2
Report Issued Date : Jun. 20, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR651207C