3. Internal Photograph of EUT

Brand Name: BLU; Model Name: Studio 5.3 II


Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO II Page Number : 11 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01




Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\scriptstyle\rm II$ Page Number : 12 of 24 Report Issued Date : Feb. 06, 2013 Report Version : Rev. 01



Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\scriptstyle\rm II$ Page Number : 13 of 24 Report Issued Date : Feb. 06, 2013 Report Version : Rev. 01


Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO II Page Number : 14 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01




Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO ${\rm I\hspace{-.1em}I}$ Page Number : 15 of 24 Report Issued Date : Feb. 06, 2013 Report Version : Rev. 01




Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO ${\rm I\hspace{-.1em}I}$ Page Number : 16 of 24 Report Issued Date : Feb. 06, 2013 Report Version : Rev. 01




Report No.: EP311601




TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO ${\rm I\hspace{-.1em}I}$ Page Number : 17 of 24 Report Issued Date : Feb. 06, 2013


Report Version : Rev. 01

Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO II Page Number : 18 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158


FAX: 86-0512-5790-0958

FCC ID: YHLBLUSTUDIO II

Page Number : 19 of 24
Report Issued Date : Feb. 06, 2013

Report Version : Rev. 01


Report No.: EP311601



SPORTON INTERNATIONAL (KUNSHAN) INC.


TEL : 86-0512-5790-0158 FAX : 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\scriptstyle\rm II$ Page Number : 20 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01

Report No.: EP311601




TEL : 86-0512-5790-0158 FAX : 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\rm II$ Page Number : 21 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01

Report No.: EP311601



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUDIO II Page Number : 22 of 24
Report Issued Date : Feb. 06, 2013
Report Version : Rev. 01






TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\scriptstyle \rm II$ Page Number : 23 of 24 Report Issued Date : Feb. 06, 2013 Report Version : Rev. 01

Report No.: EP311601





SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUSTUDIO $\scriptstyle \rm II$ Page Number : 24 of 24 Report Issued Date : Feb. 06, 2013

Report No.: EP311601

Report Version : Rev. 01