

## Appendix D. Setup Photographs

## <Conducted Emission>





SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGDXLLTE Page Number D1 of D2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0


Report No.: FR761302C



## <Radiated Emission>

X Plane

LF



HF



SPORTON International (ShenZhen) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLUGDXLLTE Page Number D2 of D2
Report Issued Date Jul. 12, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CWL Version 2.0

Report No.: FR761302C