




## Band5 / 1.4MHz / Low CH / QPSK




## Band5 / 1.4MHz / Low CH / 16QAM



## Band5 / 1.4MHz / Low CH / 64QAM



## Band5 / 1.4MHz / Mid CH / QPSK



## Band5 / 1.4MHz / Mid CH / 16QAM



## Band5 / 1.4MHz / Mid CH / 64QAM





## Band5 / 1.4MHz / High CH / QPSK




## Band5 / 1.4MHz / High CH / 16QAM




## Band5 / 1.4MHz / High CH / 64QAM




## Band5 / 3MHz / Low CH / QPSK




## Band5 / 3MHz / Low CH / 16QAM




## Band5 / 3MHz / Low CH / 64QAM









## Band5 / 5MHz / Low CH / QPSK




## Band5 / 5MHz / Low CH / 16QAM




## Band5 / 5MHz / Low CH / 64QAM




## Band5 / 5MHz / Mid CH / QPSK



## Band5 / 5MHz / Mid CH / 16QAM




## Band5 / 5MHz / Mid CH / 64QAM







## Band5 / 5MHz / High CH / QPSK




## Band5 / 5MHz / High CH / 16QAM




## Band5 / 5MHz / High CH / 64QAM




## Band5 / 10MHz / Low CH / QPSK



## Band5 / 10MHz / Low CH / 16QAM



## Band5 / 10MHz / Low CH / 64QAM







## Band5 / 10MHz / Mid CH / QPSK



## Band5 / 10MHz / Mid CH / 16QAM




## Band5 / 10MHz / Mid CH / 64QAM




## Band5 / 10MHz / High CH / QPSK





## Band5 / 10MHz / High CH / 16QAM



## Band5 / 10MHz / High CH / 64QAM










REPORT No. : SZ19100071W02


## Band7 / 10MHz / Mid CH / QPSK



## Band7 / 10MHz / Mid CH / 16QAM



## Band7 / 10MHz / Mid CH / 64QAM




## Band7 / 10MHz / High CH / QPSK



## Band7 / 10MHz / High CH / 16QAM




## Band7 / 10MHz / High CH / 64QAM






## Band7 / 15MHz / Low CH / QPSK




## Band7 / 15MHz / Low CH / 16QAM




## Band7 / 15MHz / Low CH / 64QAM




## Band7 / 15MHz / Mid CH / QPSK



## Band7 / 15MHz / Mid CH / 16QAM



## Band7 / 15MHz / Mid CH / 64QAM






## Band7 / 15MHz / High CH / QPSK




## Band7 / 15MHz / High CH / 16QAM




## Band7 / 15MHz / High CH / 64QAM




## Band7 / 20MHz / Low CH / QPSK



## Band7 / 20MHz / Low CH / 16QAM



## Band7 / 20MHz / Low CH / 64QAM






REPORT No. : SZ19100071W02


## Band7 / 20MHz / Mid CH / QPSK



## Band7 / 20MHz / Mid CH / 16QAM




## Band7 / 20MHz / Mid CH / 64QAM




## Band7 / 20MHz / High CH / QPSK



## Band7 / 20MHz / High CH / 16QAM



## Band7 / 20MHz / High CH / 64QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.  
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,  
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. ChinaTel: 86-755-36698555 Fax: 86-755-36698525  
Http://www.morlab.cn E-mail: service@morlab.cn




REPORT No. : SZ19100071W02

## Band12 / 1.4MHz / Low CH / QPSK



## Band12 / 1.4MHz / Low CH / 16QAM




## Band12 / 1.4MHz / Low CH / 64QAM



## Band12 / 1.4MHz / Mid CH / QPSK



## Band12 / 1.4MHz / Mid CH / 16QAM



## Band12 / 1.4MHz / Mid CH / 64QAM



MORLAB

SHENZHEN MORLAB COMMUNICATIONS TECHNOLOGY Co., Ltd.  
FL1-3, Building A, FeiYang Science Park, No.8 LongChang Road,  
Block67, BaoAn District, ShenZhen , GuangDong Province, P. R. China

Tel: 86-755-36698555 Fax: 86-755-36698525  
Http://www.morlab.cn E-mail: service@morlab.cn