


## Appendix A. Setup Photographs

## <Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD60LTE Page Number : A1 of A3

Report No.: FR492904C


Report Issued Date : Nov. 14, 2014 Report Version : Rev. 01




## <Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD60LTE Page Number : A2 of A3
Report Issued Date : Nov. 14, 2014
Report Version : Rev. 01


Report No.: FR492904C






**Z** Plane

LF



HF



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUSTUD60LTE Page Number : A3 of A3 Report Issued Date : Nov. 14, 2014

Report No. : FR492904C

Report Version : Rev. 01