




Page Number : A91 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A92 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A93 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A94 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A95 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A96 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A97 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A98 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A99 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A100 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A101 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A102 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A103 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A104 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A105 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A106 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A107 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A108 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A109 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A110 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A111 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A112 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01


## **Conducted Spurious Emission**




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: YHLBLULIFEXL Page Number : A113 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A114 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A115 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A116 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01




Page Number : A117 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A118 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A119 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01



Page Number : A120 of A150
Report Issued Date : Dec. 02, 2015
Report Version : Rev. 01