

Appendix B. Setup Photographs

<Conducted Emission>



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : B1 of B3
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01


Report No.: FR260505B



<Radiated Emission>

X Plane

Low Frequency



High Frequency



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : B2 of B3
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01

Report No. : FR260505B




Report No.: FR260505B

Z Plane

Low Frequency



High Frequency



TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDECOXT Page Number : B3 of B3
Report Issued Date : Jun. 26, 2012
Report Version : Rev. 01