

Report No.: FC342204

Appendix B. Setup Photographs

<Conducted Emission>

Mode 1



Mode 4



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID : YHLBLUDASHMUSIC Page Number : B1 of B2 Report Issued Date: May 27, 2013 Report Version : Rev. 01




Report No.: FC342204


<Radiated Emission>

Mode 4

LF



ΗF



SPORTON INTERNATIONAL (KUNSHAN) INC.

TEL: 86-0512-5790-0158 FAX: 86-0512-5790-0958 FCC ID: YHLBLUDASHMUSIC Page Number : B2 of B2
Report Issued Date : May 27, 2013
Report Version : Rev. 01